





Gap around end of filter due to wrong size filter or poorly sized filler



Gap created by manufacturer



Outside
Air Intake

Bath
Exhaust
Fan

13 feet



Outside
Air Intake

Bath
Exhaust
Fan

Added
Extension

Outside
Air Intake

Sewer
Vent
Pipe



